STAFF ANALYSIS OF Resolution FY24-18 SCRTD

Requested Action

Approval of SCRTD to allow the disposal of the Buses 2016 Ford F-5G(Bus 2) 2016 Ford F-5G(Bus 4) 2010 Ford Econoline(Bus 733) 2011 Ford Econoline(Bus 734) 2013 Ford Econoline(Bus 743)

Reason for Request

Bus #2

- Has accident Damage; an estimated cost of repair is \$4,675.30.
- The bus also needs a new transmission; the cost of repair is \$4,000.
- NMDOT estimated value of the bus once repairs are completed is under \$5,000, (staff's estimate to repair the bus \$8,675.30).
- The Bus meets the requirements for disposal and removal from the SCRTD fleet.
- According to NMDOT table bus meets the disposable guidelines by minimum useful life and miles.

Bus #4

- Needs Engine, estimated cost of value \$5,000 or more
- The bus has been back and forth with Viva Ford dealership and Uncle Bob's garage for repairs.
- One engine was purchased from Auto Zone and bus did not run.
 Another engine was given with a warranty, and the bus was still not running.
- NMDOT estimated value of the bus once repairs are completed is under \$5,000, (staff's estimate to repair the bus \$5,000).
- The Bus meets the requirements for disposal and removal from the SCRTD fleet
- According to NMDOT table bus meets the disposable guidelines by minimum useful life and miles.

Bus 733

- Needs Engine & transmission. Estimated cost of repair \$8,308.03
- NMDOT estimated value of the bus once repairs are completed is under \$5,000, (staff's estimate to repair the bus \$8,308.03).
- The Bus meets the requirements for disposal and removal from the SCRTD fleet
- According to NMDOT table bus meets the disposable guidelines by minimum useful life and miles.

Bus 734

- Has accident damage and also needs transmission. Estimated cost of repairs \$5,119.14 parts only
- NMDOT estimated value of the bus once repairs are completed is under \$5,000, (staff's estimate to repair the bus \$5,119.14 or more).
- The Bus meets the requirements for disposal and removal from the SCRTD fleet
- According to NMDOT table bus meets the disposable guidelines by minimum useful life.

 Bus 743
 Needs body harness, wiring harness. Will have to get with Creative Bus sales to order the harness. Or It will have to be custom made because of the year of the bus.

- After being driven it starts to heat up and the wires start to burn and melt causing electrical fire.
- Maintenance has been fixing one thing and another one breaks.
- NMDOT estimated value of the bus once repairs are completed is under \$5,000, (staff's estimate to repair the bus is more than \$5,000).
- The Bus meets the requirements for disposal and removal from the SCRTD fleet
- According to NMDOT table bus meets the disposable guidelines by minimum useful life and miles.

Analysis

The SCRTD Property Disposal Standing Committee met on November 2023 and recommended the disposal of all buses.

South Central Regional Transit District INSPECTION AND CONDEMNATION REPORT/FIXED ASSET TRANSFER FORM

Sold Sold Sold Sold Sold Sold Sold Sold	of Condemnation: below is unusable to the degree titeria. book Value: bree if over \$5,000: below: bree Identification (VIN) #	□ Negotiated Sale □ Contract Sale □ Competitive Bid □ Donation hat it is no longer economi Year, Make & Mod	cal to ma	Destroy Public Auction General Services I Commercial Landi aintain as part of the S	ill or	v v	following reason Obsolete Excessively Costly to Repair Not Usable anywhere in the organzation	€
Solo Salv Oth Justification of The vehicle buseful life crit Estimated Bo Funding Sour Rolling Stock Bus # Veh 2 4 733 734 743	Id -Still Useable Ivage for parts her of Condemnation: below is unusable to the degree titeria. book Value: cree if over \$5,000: k Only: hicle Identification (VIN) #	☐ Contract Sale ☐ Competitive Bid ☐ Donation hat it is no longer economi Year, Make & Mod	□ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □	Public Auction General Services E Commercial Lands aintain as part of the S	ill or	v v	Obsolete Excessively Costly to Repair Not Usable anywhere in the organzation	€
Oth Justification of The vehicle b useful life crit Estimated Bo Funding Sour Rolling Stock Bus # Veh 2 4 733 734 743	her of Condemnation: below is unusable to the degree titeria. ook Value: rce if over \$5,000: k Only: hicle Identification (VIN) #	☐ Competitive Bid ☐ Donation hat it is no longer economi Year, Make & Moe	□ ☑	General Services E Commercial Landf aintain as part of the S	ill or	Ø	Costly to Repair Not Usable anywhere in the organzation	
Oth Justification of The vehicle b useful life crit Estimated Bo Funding Sour Rolling Stock Bus # Veh 2 4 733 734 743	ther of Condemnation: below is unusable to the degree to iteria. book Value: tree if over \$5,000: k Only: hicle Identification (VIN) #	□ Donation hat it is no longer economi Year, Make & Mod	cal to ma	Commercial Landf	ill or		Not Usable anywhere in the organzation	
Justification of The vehicle buseful life crit Estimated Bo Funding Sour Rolling Stock Bus # Veh 2 4 733 734 743	of Condemnation: below is unusable to the degree titeria. book Value: bree if over \$5,000: below: bree Identification (VIN) #	hat it is no longer economi Year, Make & Mod	cal to ma	aintain as part of the S	SCRTD flee	t and m		stration's
The vehicle b useful life crit Estimated Bo Funding Sour Rolling Stock Bus # Veh 2 4 733 734 743	below is unusable to the degree to teria. book Value: coe if over \$5,000: k Only: hicle Identification (VIN) # 1FDGF5GY3GEA51958	Year, Make & Mod		aintain as part of the S	SCRTD flee	t and m	eets FTA adminis	stration's
useful life crit Estimated Bo Funding Sour Rolling Stock Bus # Veh 2 4 733 734 743	iteria. ook Value: ree if over \$5,000: k Only: hicle Identification (VIN) #	Year, Make & Mod				t and m	eets FTA adminis	tration's
useful life crit Estimated Bo Funding Sour Rolling Stock Bus # Veh 2 4 733 734 743	iteria. ook Value: ree if over \$5,000: k Only: hicle Identification (VIN) #	Year, Make & Mod						
Funding Sour Rolling Stock Bus # Veh 2 4 733 734 743	k Only: hicle Identification (VIN) #	·	del	Acquisition Date				
Rolling Stock Bus # Veh 2 4 733 734 743	k Only: hicle Identification (VIN) # 1FDGF5GY3GEA51958	·	iel .	Acquisition Date				
Bus # Veh 2 4 733 734 743	hicle Identification (VIN) # 1FDGF5GY3GEA51958	·	del	Acquisition Date				
2 4 733 734 743	1FDGF5GY3GEA51958	·	del	Acquisition Date				
733 734 743		2017 EODD E 57		•	Miles	as of	EST. Cost to Repair	Remarks
733 734 743	1EDGEEGVGE LEIGES	2016 FORD F-50		11/23/2015	296,	160	\$8,675.30	See Staff Analysis for reference
734 743	1FDGF5GYGEA51952	2016 FORD F-50	3	11/18/2015	192,		\$5,000	See Staff Analysis for reference
743	1FDFE4FS8AD68743	2010 FORD ECONO		8/29/2016	247,		\$8,308.03	See Staff Analysis for reference
	1FDFE4FS5BDB05247	2011 FORD ECONO		3/13/2012	213,	377	\$5,119.14	See Staff Analysis for reference
	1FDFE4FS0DDA09352	2013 FORD ECONO		5/2/2022	268,	880	\$5,000 or more	See Staff Analysis for reference
	ertify that the information herein y: Property disposal committee	is true, to the best of our k	.iiow teag	ge and better				
Exe	ecutive Director / David Armijo	Date			CFO/ Sara	ı Vasqu	ez	Date
signature								
Fina	nance Officer/ Adam Shea	Date						
					Chair Pers	son/ Jav	ier Perea	Date
PROPOSED	FINAL DISPOSITION CON	TENGENT UPON 30 DA	Y REV	IEW BY THE OFFI	CE OF TH	E STA	TE AUDITOR	
	ition: (Provide details of who sol							
						-		
Printed Name	e & Signature	Date		Title		_	<u>=</u> :	
Issuing Office	e sends Original to Fixed Assets	Administrator						

11

 \mathbf{v}



VEHICLE DISPOSITION PROCEDURES

April 2023

NMDOT may approve the disposition of any vehicle, regardless of funding source, if it is to be replaced with Federal Transit Administration (FTA) funds.

The NMDOT will remain the lien holder on the title to any vehicles purchased with FTA funds until its final disposition. Under normal circumstances, NMDOT will only consider disposition of a vehicle in any category that has met the minimum useful life benchmark in either years or miles (which ever happens first) according to the following schedule and if vehicles are no longer in a state of good repair or can no longer be maintained to a state of good repair within reasonable measures:

	Typica	al Characteristics	Mi	nimum Life
Category	Approx. GVW	Average Cost	Years	Miles
Heavy-Duty Large Bus	33,000 to 40,000	\$325,000 to over \$600,000	15	625,000
Heavy-Duty Small Bus	26,000 to 33,000	\$200,000 to \$325,000	13	455,000
Medium-Duty and Purpose- Built Bus	16,000 to 26,000	\$75,000 to \$175,000	10	285,000
Light-Duty Mid-Sized Bus	10,000 to 16,000	\$50,000 to \$65,000	8	240,000
Light-Duty Small Bus, Cutaways, and Modified Van	6,000 to 14,000	\$30,000 to \$40,000	7	175,000

Subrecipients may replace a non-FTA-funded vehicle with an FTA-funded vehicle. As with FTA-funded vehicles, the vehicle(s) to be replaced must have met the useful life benchmark in either years or miles.

NMDOT may also approve the disposition of a vehicle before the end of useful life if a subrecipient demonstrates that continuing to operate and maintain the vehicle is not cost effective, the vehicle is unsafe, or the insurance company has totaled the vehicle as a result of an accident.

Subrecipients use BlackCat to request disposition of any vehicle listed in the BlackCat asset inventory, even those not funded with FTA funds.

Bus 2 pictures























661518			670659		670666		683072		699121	703303										739790		739792				758646		776191		//5/24				796134				861282				
6615181 Bus #2			6706591 Bus #2		6706661 Bus #2		6830729 Bus #2		6991215 Bus #2	7033035 Bus #2										7397903 Bus #2	-	7397922 Bus #2				7586468 Bus #2		7761911 Bus #2		//5/244 Bus #2				7961348 Bus #2				8612822 Bus #2				
156171 mi			158089 mi		158090 mi	-141	161220 mi		164448 mi	165316 mi										168300 mi		168300 mi				173403 ml		176788 mi		1/6899 mi				182388 mi				197654 mi)			
Replacement	Replacement Brake Pad(s)	Brake Rotor	Replacement	Brake Pad(s) Replacement Water Pump	Oil Change		Engine Belt Inspection		Engine Belt Inspection	Replacement seals brakes	Replacement Brake Rotor	Replacement Brake Pad(s)	inspection Air Fitter	Transport of the state of the s	De la companya del companya de la companya del companya de la comp	Tires Battery	Inspection Rotate	Oil Change Engine Bett		Engine Belt Inspection		Replacement	Replacement Thermostat	Manifold Gasket	Rotate Tires Intake	Oil Change		Battery Replacement		Inspection	Inspection Engine Belt	Inspection Battery	Rotate Tires Brake	Replacement	Inspection Air Filter	Tires Engine Belt	Oil Change Rotate	Inspection	Inspection Battery	Inspection Brake	Tires Engine Belt	Oil Change Rotate
	SCRTD			SCRID	facility	SCRTD	facility	SCRTD	SCRTD	1	SCRTD	_								facility	SCRTD	facility				facility	SCRTD	facility	SCRID	racility	SCRID			facility	SCRTD			facility	SCRTD			
Brake service			water pump		oil change		belt		belt	oil change										belt		Tires				oil change		battery		belt				oil change				oil change				
squeaking	Brakes		coolant leak				BELT		belt	OIL CHANGE										belt		Tires				pm	OIL CHANGE	battery		irres				OIL CHANGE				OIL CHANGE				
1/28/2020 17:02			2/10/2020 13:10		2/10/2020 13:23		2/27/2020 16:56		4/3/2020 13:16	4/16/2020 16:46										6/30/2020 13:36		6/30/2020 16:39				8/11/2020 17:37		9/10/2020 15:42		9/10/2020 16:59				10/14/2020 13:21				1/9/2021 15:00				
294.77 1			0 1		30.63 1		01		0 1	306.87 1										0		564 1				0 1		135 1		0	Ú.			50.99 1				58 1				
294.77 1FDGF5GY3GEA51958			0 1FDGF5GY3GEA51958		30.63 1FDGF5GY3GEA51958		0 1FDGF5GY3GEA51958		0 1FDGF5GY3GEA51958	306.87 1FDGF5GY3GEA51958										0 1FDGF5GY3GEA51958		564 1FDGF5GY3GEA51958				0 1FDGF5GY3GEA51958		135 1FDGF5GY3GEA51958		0 THUGHSGY3GEASTSS8				50.99 1FDGF5GY3GEA51958				58 1FDGF5GY3GEA51958				



12:	12	12	13	
158412	518932	74203	123479	
12158412 Bus #2	12518932 Bus #2	12742037 Bus #2	13234796 Bus #2	
Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	
		Non-Scheduled	Non-Scheduled	
254862 mi	262596 mi	265257 mi	267183 mi	
3,	ni.	=	3	
Engine Belt Inspection Engine Oil & Filter Replacement Engine Coolant Replacement Battery Inspection Brake Inspection Tire Rotation Air Filter Replacement Battery Inspect Windshield Washer Fluid Fill, fuel injector Service	Engine Oil & Filter Replacement Engine Belt Inspection Battery Inspection Brake Inspection Tire Rotation Windshield Wiper Blade Replacement Windshield Washer Fluid Fill fuel Injector service	Radiator Fan Clutch Replacement Thermostat Replacement Engine Coolant Drain & Refill Engine Coolant Replacement Engine Belt	Pug Replacement Engine Coolant Replacement Crossover Bypass Tube Drive Bett Idles Putley Assembly Replacement Intake Manifold Gasket Replacement Tire Replacement Tire Replacement Tire Replacement Tire	Brake Inspection Brake
r SCRTD facility	SCRTD	SCRTD	SCRTD SCRTD SCRTD	
₹	₹	FAN CLUTCH	rear brakes SPARK PLUGS	
steven and	Humberto + Cruz	CRUZ /	Humberto	
3/26/2022 12:52	4/29/2022 10:26	5/17/2022 0:00	6/13/2022 0:00	
58.531	49.28	124.16	767.89	
58.53 1FDGF5GY3GEA51958	1FDGF5GY3GEA51958	124.16 1FDGF5GY3GEA51958	767.89 1FDGF5GY3GEA51958	

9056146 Bus #2	9699783 Bus #2	9823049 Bus #2	98/1233 Bus #2			10031922 Bus #2		10275074 Bus #2		10560804 Bus #2	11346565 Bus #2
Bus #2	Bus #2	Bus #2	Bus #2			Bus #2					
								Albert Minjares		Atbert Minjares	Albert Minjares
	\$)										
205408 mi	221085 mi	223879 mi	224575 mi			228637 mi		232932		236628 m	243893 m
	⊞i	∄				3		B	ĺ	T .	3
Oil Change Engine Belt Inspection Rotate Tires Radiator Replacement Water Pump	Brake Pad(s) Replacement Rotate Tires Engine Bett Inspection Oil Change Battery Inspection Brake Inspection Brake Inspection Air Filter Replacement Tire Replacement Windshield Wiper Blade Replacement	Tire Replacement	Charges	Replacement power booster Admin/Misc	Power Steering Line	Filter Replacement	Inspection Battery Inspection Air Filter Inspection Air Filter Replacement Engine Oil &	Replacement	Carpantina Ralt	Engine Oil & Filter Replacement Engine Belt Inspection Brake Inspection Battery Inspection Tire Rotation Air Filter Replacement Windshield Washer Fluid Fill	Engine Belt Inspection Engine Oil & Filter Replacement Battery Inspection Brake Inspection Tire Rotation Air Filter Replacement fuel injector service Windshield Washer Fluid Filt
SCRTD	SCRTD Scrity	SCRTD	facility	SCRTD		facility	SCRTD	facility	CTBCS		r SCRTD SCRTD
oil change	oil change	Diagnosis	service	6	ĸ	oil change				3	3
OIL CHANGE	OIL CHANGE	Tires	service				OIL CHANGE	Steven		steve	Steven &
3/6/2021 14:40	6/30/2021 12:44	7/23/2021 21:17	7/30/2021 17:43			9/1/2021 21:24		10/14/2021 17:15	***************************************	11/17/2021 18:13	1/26/2022 9:23
333	348.98	345	252.08		0	91 69		32.99	07.00	37.65	46.14
223 1EDGEEGY3GEAS1050	348.98 1FDGF5GY3GEA51958	345 1FDGF5GY3GEA51958	252.08 1FDGF5GY3GEA51956		1 200 001000000000000000000000000000000	91 69 150055507305451959		32.99 1FDGF5GY3GEA51958	TI 001 001 001 001 001	37.65 1FDGF5GY3GEA51958	46.14 1FDGF5GY3GFA5135R

15014062 Bus #2	15355109 Bus #2	15695771 Bus #2	16128013 Bus #2	16905724 Bus #2	Fleetio ID
Bus #2	Bus #2	Bus #2	Bus #2	Bus #2	Vehicle Name
Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Watchers
Non-Scheduled	Scheduled	Scheduled	Non-Scheduled	Scheduled	Repair Priority Class
281135 m	282190 mi	290131 mi	291705 mi	296159 mi	Meter
m	3	3	Ξ.	3	Meter Unit
Power Steering Fluid Fill Engine Belt Inspection	Transmission Fluid Drain & Refill Engine Bett Inspection Brake Inspection Battery Inspection	Engine Oil & Filter Replacement fuel injector service Tire Rotation Tire Replacement Tire Replacement Tire Balance Engine Air Filter Replacement Windshield Washer Fluid Filt Engine Coolant Filt Electrical System (Miscellaneous) Engine Belt Inspection Barke Inspection Battery Inspection Air Filter Replacement	Radiator Replacement Engine Coolant Drain & Refill Air Conditioning Refrigerant Lines Inspect A/C HOSE A/C System Evacuate & Recharge	Engine Oil & Filter Replacement Engine Belt Inspection Battery Inspection Brake Inspection Tire Rotation	Service Tasks
SCRTD facility	SCRTD	SCRTD facility	SCRTD	SCRTD facility	Vendor Name
Power Steeering Humberto	transmission	P X	RADIATOR	P	Labels
Humberto	Cruzand	Humberto tina	Humberto	Humberto and Albert	Reference
10/4/2022 0:00	11/8/2022 0:00	1/10/2023 0:00	2/6/2023 0:00	3/22/2023 0:00	Completed At
9.99	7	449.18	60.18	28.69	Parts Subtotal (USD)
9.99 1FDGF5GY3GEA51958	77 1FDGF5GY3GEA51958	449.18 1FDGF5GY3GEA51958	60.18 1FDGF5GY3GEA51958	28.69 1FDGF5GY3GEA51958	Vehicle VIN/SN

13534522 Bus #2	13844517 Bus #2	13844146 Bus #2	14061042 Bus #2	14341638 Bus #2
Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares
Scheduled	Emergency	Emergency	Emergency	Scheduled
269925 mi	271668 mi	272763 mi	276505 mi	279171 mí
Engine Oil & Filter Replacement Engine Belt Inspection Tire Rotation Battery Inspection Brake Inspection Air Filter Replacement Brake Pad(s) Replacement Engine Drive Belt Replacement fuel Injector service	Engine Coolant Thermostat Replacement Engine Coolant Drain & Refil. Engine Bett Inspection Battery Inspection	Headlamp Bulb Replacement Engine Bett Inspection Battery Inspection Brake Inspection	Tire Rotation Power Steering Line Replacement Power Steering Fluid Fill	Replacement Engine Belt Inspection Brake Inspection Battery Inspection Battery Inspection Air Filter Inspection Windshield Washer Fluid Filt Engine Coolant Filt Suspension System Lubricate wheel chair lift Brake Pads Replacement Shock or Strut Replacement Disc Brake Caliper Replacement Brake Rotor Replacement Bra
SCRTD	SCRTD	SCRTD facility	SCRTD	SCRTD SCRTD
¥	COOLING	headlight	Power Staeering Humberto	¥
CRUZ /	HUMBERTO	нимвекто	g Humberto	Cruz and
7/8/2022 0:00	7/20/2022 0:00	7/26/2022 0:00	8/15/2022 0:00	9/10/2022 0:00
194.98 JFDGF5GY3GEA51958	10.6 1FDGF5GY3GEA51958	16.49 1FDGF5GY3GEA51958	20.69 1FDGFSGY3GFA51958	523.71 1FDGF5GY3GF451958

Aaron's Truck & Body Repair



9010 Curtis Dr. • Canutillo, Texas 79835 (915) 267-7150

AME:	SCRTU	ADDRE	ss:830 Anthony	dr.	BUS.	船(5)3	23-1620
8700 .	2016 FC	RDF550 ADJUS	TER:	Valletin	PHON	E:	
YEAR	AND MAKE	BODY STYLE	SERIAL#	LI			LEAGE
ate:			-A51950	996			159
RE-	DE	TAILS OF REPAIRS AND/OR	REPLACEMENTS TO BE MADE		HOURS LABOR	PARTS AT LIST	SUBLET AND NET ITEMS
	REAR L	EFT SIDE PA	NWEL ANDREAR	BU3			
	PANNEL	DIVIDING MI	OLDING REFLAC	E	2.5		
	REAR F	BUMPER /UNS	TIALL & REPLAC	E	15		
V	REAR P	UMPER BRAC	KET REPATR	WELD"	2.5		
	\\ Bo	DY & FIBER	SLASS REPAT	R"			
V	REAR	LEFT BUDY	PHINNEL REP	HIR \	13		
	REAR	PANNEL FI	BERG, BOTTOM	CORNERI			
V	REAR F.	IBERGLASS PA	INNEL REPAIR /R	EAR			
	12116 11/2	ENDOW REWICH	L FUD JOB PER	FOR-	7.5		
	- MANCE	\$ RETUSTH	LL "RESEAL"	/ /			
	" PA	THIT PRED -	PRIMER /SAND	MASK			
	LEFTRE	HR PHANEL.	HND FIBERGLA	155-	17		
	-REAR K	HANNEL /BUM	PER "REAR"	7			
	*	PHINT MATER	THE COST"	#	688	30	
	" PA	RTS REPLAC	E"				
	REH	R BUMPER		#	565	00	
	REA		LDING "SID.	E" #	122	,00	
-	7,127,	1202 18:00					
1		****					
-							
	ESTIMATE	OF REPAIR COSTS	THE STATE OF THE S	OTALS			
Th parts or	a shoup is an estimate o	n our Inspection and does not cave lied after the work has been opened of d or broken parts are discovered which	r any additional	OTALO		d	
after the	irst inspection.		n are not evident Wrecker &	Storage			. \$
Sign	THE STATE OF THE S	nsible for Fire, Theft, or Vandalism	Total Hours		_@_2	75.00	. \$
_	/ 5	injars	Parts \$	Le	88 % _		\$ 66 F.C
Ву	Tipe 1 /VI	injaies	Sublet and	Net Items			_ \$
			Sales Tax_	15-34-14		TOTAL	:41.75

Bus 4 Pictures



















6338959	6729096	6768204	6893907	7101493	7101484	7604396	10806003	Fleetio ID
Bus #4	Bus #4	Bus #4	Bus #4	Bus #4	Bus #4	Bus #4	Bus #4	Vehicle Name
							Albert Minjares	Watchers
174733	174806	181223	184637	189300	189300	192525	192647	Meter
3.	3.	⊒.	m,	3,	D.	₽,	3.	Meter Unit
	Oil Change	Oil Change	Engine Belt Inspection	Engine Belt Inspection	Oil Change Spark Plug Replacement	Oil Change Rotate Tires Engine Belt Inspection Tire Replacement	Brake Inspection Battery Inspection Engine Bett Inspection Air Filter Replacement Engine Oil & Filter Replacement Tire Rotation Engine Coolant Replacement Spark Plug Replacement Engine Drive Bett Replacement Engine Drive Bett Replacement Engine harness replace Engine replaced	Service Tasks
SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	Uncle Bob's Garage	Vendor Name
		oil change	belt	belt	OIL oil change CHANGE	oil change	engine	Labels
		OIL	bett	belt	OIL CHANGE	OIL CHANGE pm		Reference
12/16/2019 14:17	12/16/2019 16:42	2/12/2020 9:28	3/9/2020 13:54	5/6/2020 13:15	5/6/2020 17:11	8/14/2020 17:37	12/15/2021 15:20	Completed At
0	25	38	0	0	132.9	335	Ö	Parts Subtotal (USD)
2016	2016	2016	2016	2016	2016	2016	2016	Vehicle Year
Ford	Ford	Ford	Ford	Ford	Ford	Ford	Ford	Vehicle Make
F-550 Super Duty	F-550 Super Duty	F-550 Super Duty	F-550 Super Duty	F-550 Super Duty	F-550 Super Duty	F-550 Super Duty	F-550 Super Duty	Vehicle Model
1FDGF5GY2GEA51952	1FDGF5GY2GEA51952	1FDGF5GY2GEA51952	1FDGF5GY2GEA51952	1FDGF5GY2GEA51952	1FDGF5GY2GEA51952	1FDGF5GY2GEA51952	1FDGF5GY2GEA51952	Vehicle VIN/SN

	v.		

Bus 733 Pictures















Bus 733 Pictures



















SCRTD WORK ORDER

Submitted by:

Date:

Bus:

Remarks:

Milleage: 733

1FDFE4F\$810168743 2010 Ford F-450

CIPPS T		<u> </u>	0	TXAOB3	52 0			NUMBER
sim las	Transmission Sluid	Trans wission	Oil transment	(solan)	Oil Silter	Oil Buso	Engine	018
Trensmission oil Cooler	on Sluid	05	men t			30		DESCRIPTION
Diralest	X-ReV		Lucas	Shop Pro	d15			BRAND
	1651	-	127	50	_	694	/	QUANTITY
	5.20			_		2.25 13.50		PRICE
237.99	83.2	2749	9.60	8.99 44.95	2.79	13.50	5767	AMOUNT

TOTAL: 8,308.03

	6345278	6345232	6770211	6894227	7150255	7150243	7150225	7643818	8342903
	Bus #733	Bus #733	Bus #733	Bus #733	Bus #733	Bus #733	Bus #733	Bus #733	Bus #733
	141000	141876	148011	151085	157140	157140	157140	166938	179283
	3	3	∄	3.	æ	2,	3	THE	mi
Ser	windshield replace	Oil Change	Oil Change Brake Rotor Replacement Brake Inspection Brake Pad(s) Replacement Rotate Tires	Engine Belt Inspection	Engine Belt Inspection	Oil Change	Rotate Tires	Oil Change Rotate Tires Engine Belt Inspection Brake Inspection Battery Inspection	Engine Belt Inspection Oil Change Rotate Change Rotate Tires Battery Inspection Brake Inspection Air Filter Replacement
	Rogers Auto Glass	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD	SCRTD facility	SCRTD facility
		oil change	Brake	belt	belt	oil change	Tires	oil change	oil change
			OIL	belt	belt	OIL	Tires	OIL CHANGE	OIL CHANGE
	12/13/2019 12:00	12/18/2019 14:14	2/14/2020 1:36	3/10/2020 12:46	5/15/2020 12:50	5/15/2020 16:48	5/15/2020 17:47	8/20/2020 16:59	11/1/2020 13:04
	0	19.94	45	0	0	48	0	25	193
	2010	2010	2010	2010	2010	2010	2010	2010	2010
	Ford	Ford	Ford	Ford	Ford	Ford	Ford	Ford	Ford
	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis
	E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD
	Bus	Bus	Bus	Bus	Bus	Bus	Bus	Bus	Bus
	1FDFE4FS8ADA68743	1FDFE4FS8ADA68743	1FDFE4FS8ADA68743	1FDFE4FS8ADA68743	1FDFE4FS8ADA68743	1FDFE4FS8ADA68743	1FDFE4FS8ADA68743	1FDFE4FS8ADA68743	1FDFE4FSBADA68743

	.!		
		1	
ii.			

113:	112	114	115	Fig
11335981	11285788	11466039	11517196	Fleetio ID
Bus #733	Bus #733	Bus #733	Bus ⊭733	Vehicle Name
Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Watchers
239761	240672	245790	246069	Meter
<u> </u>	3.	∄	Э	Meter Unit
Engine Belt Inspection Engine Oil & Filter Replacement Battery Inspection Brake Inspection Tire Inspection Tuel Injector service Windshield Washer Fluid Fill Engine Oil Pan Gasket Transmission Shifter Lever Engine Drive Belt Replacement	Headlamp Buib Replacement	Engine Coolant Replacement Brake Inspection Engine Belt Inspection	Engine Oil & Filter Replacement Engine Belt Inspection Battery Inspection Tire Rotation Brake Inspection Air Filter Replacement Transmissio n Fluid Drain & Refill Transmission Filter Replacement Transmissio n Guide Drain & Refill Transmissio Filter Replacement Transmissio n (Wiscellaneous) Windshiel d Washer Fluid Fill fuel injector service	Service Tasks
SCRTD	SCRITD facility	SCRTD	SCATD	Vendor Name
oil pan gasket P M	headlight	COOLANT	PM	Labels
Ruben & art & Albert	ruben	Steven	RUBEN	Reference
1/6/2022 10:10	1/15/2022 11:40	2/14/2022 11:39	2/18/2022 13:45	Completed At
140.01	4.39	26.97	174.63	Parts Subtotal (USD)
2010	2010	2010	2010	Vehicle Year
Ford	Ford	Ford	Ford	Vehicle Make
E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	Vehicle Model
E-450 SD	E-450 SD	E-450 SD	E-450 SD	Vehicle Trim
Bus	Bus	Bus	Bus	Vehicle Type
1FDFE4FS8ADA68743	1FDFE4FS8ADA68743	1FDFE4FSBADA68743	1FDFE4FSBADA68743	Vehicle VIN/SN

8662907	9056268	9663908	9967562	10231230	10607619
Bus #733	Bus #733	Bus #733	Bus #733	10231230 Bus #733	Bus #733
				Albert Minjares	Albert
190266	196950	213778	222053	229006	235841
3	⊒	⊒,,	m	លាំ	3
Oit Change Engine Bett Inspection Rotate Tires Brake Pad(s) Replacement Air Filter Replacement	Oil Change Battery Inspection Brake Inspection Rotate Tires Engine Belt Inspection Air Filter Replacement Starter Replacement	Oil Change Rotate Tires Engine Belt Inspection Battery Inspection Brake Inspection Tire Replacement	Oil Change Rotate Tires Engine Belt Inspection Brake Inspection Air Filter Replacement	Battery Inspection Engine Bett Inspection Oil Change Brake Inspection Rotate Tires Air Filter Replacement Tire Replacement fuel injector service	Engine Belt Inspection Engine Oil & Filter Replacement Brake Inspection Battery Inspection Tire Rotation Brake Pad(s) Replacement Air Filter Replacement Windshield Washer Fluid Fill fuel injector service Engine Drive Belt Replacement
SCRTD facility	SCRTD	SCRTD facility	SCRTD	SCRID facility	SCRTD
oil change	oil change	oil change	service	oil change (Ti res	FRONT BRAKES P M rear brakes
OIL CHANGE pm	OIL CHANGE pm	OIL CHANGE pm	OIL CHANGE pm	oil change TI Ruben and res Albert	RUBEN
1/15/2021 21:04	3/6/2021 11:03	6/25/2021 11:29	8/23/2021 20:29	10/12/2021 9:12	11/29/2021 10:54
137	71	238	71	247.98	159.33
2010	2010	2010	2010	2010	2010
Ford	Ford	Ford	Ford	Ford	Ford
E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis
E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD
Bus	Bus	Bus	Bus	Bus	Bus
1FDFE4FS8ADA68743	1FDFE4FS8ADA68743	1FDFE4FS8ADA68743	1FDFE4FS8ADA68743	1FDFE4FS8ADA68743	1FDFE4FS8ADA68743

Bus 734 Pictures















SCRTD WORK ORDER

Bus;	Date:	Submitted by:
734		

Gre	004	M102910 In	15245 Hub Sec)	CMIDZACA OUT	3ml 12135	42264 Righ		Treu	Treu	Toes	NUMBER
Granse-high trup	outter bearing Ruce	LM102910 Inner beging Race	Seel	MIDZAL Outter beering	Inner bouring	Right front Rotor/hub	Right Sout Spindle	Transmission oil Cooler	Transmission Fluid	Trensmission	OF CIVIT II OIN
	1	4		Duralest	Dufa last	hub	1) = Notercraft	ooler	<u>a</u>		BRAND
1 hube	-		_	7		_	_	\	1654	/	QUANTITY PRICE
6.00	6.19	6.79	5.99	(1.99	18-21	16037	164.0	23799	165+ 5.20 83.20	2749	PRICE AMOUN

SCRTD WORK ORDER

•				
. 1				
· * 1				
311.84		boshader	render flage	72005-11 Te
7424	_	-314	ha front head lung wholly	-02501177 R.
1200	-		Bike ruck	
131.0%	_		and bumper	25.
[[1.20	_		ill assembly	90
84.39	_		Right Smant Fember	Q.
TY PRICE AMOUNT	QUANTITY	BRAND	DESCRIPTION	NUMBER
				DABE
			• ,	Remarks:
				Milleage:
			734 Cont.	Bus:
				Date:
				Submitted by:

TOTAL: 5,119.14

Parts only

1FDFE4FS56D805247	Bus	E-450 SD	E-Series Chassis	Ford	2011	25	12/2/2019 9:59			SCRTD *acility	Oil Charge	3	170662	Bus 9734	6729277
1FDFE4FS5BDB05247	Bus	7456 80	E-Series Chassis	Ford	2011	38	2/12/2020 9:30	CHAMICE	oil change	SCRTD facility	Oil Change	3	150185	Bus 4734	6748452
1FDFE4FS5BDB0S247	Bus	05 05P-3	E-Series Chassis	Ford	2011	0	3/5/2020 13:17	belt	belt	SCRTD facility	Engine Belt Inspection	2	163261	Bus #734	6866874
1FDFE4FS58DB05247	Bus	E-450 SD	E Series Chassis	Ford	2011	0	4/2/2020 9;45	battery	battery	SCRTD facility	Battery Inspection	3	187161	Bus #734	7166234
1FDFE4FSSBDB05247	Bus	E-450 SD	E-Series Chassis	Ford	2011	0	4/2/2020 8:59	Tires	Tires	SCRTD	Rotate Tires	Ð	187161	Bus ≓734	7150299
1FDÆ4FS58D805247	Bus	E-450 SD	E-Series Chassis	Ford	2011	46	4/2/2020 9:08	bett	лэс	SCRID facility	Engine Bett Inspection	3	187161	Bus #734	7150349
1FDFE4F\$58D805247	Bus	E-450 SD	E-Series Chassis	Ford	2011	o	4/2/2020 11:16	belt	belt	SCR7D facility	Engine Belt Inspection	3,	187161	Bus #734	7166225
1FDFE4FS5BDB05247	Bus	E-450 SD	E-Series Chassis	Ford	2011	65.69	4/2/2020 10:26	OIL	oil change	SCRTD	O)! Change [Engine/Drive Belt(s) Repiacement [Engine Belt Inspection	.3	187161	Bus #734	6984884
1FDFE4FSSBDB05247	8118	E-450 SD	E-Series Chassis	Ford	2011	Р	5/21/2020 9:45	belt	pel!	SCRTD	Engine Belt Inspection	ā	192822	Bus \$734	7166252
1FDFE4FS5BDB05247	Bus	E-#50 SD	E-Senes Chassis	Ford	2011	As .	6/9/2020 12:29	CHANGE	oil change	SCRID facility	Oil Change	5	194440	Bus #734	7236601
1FDFE4FS58D805247	Bus	E-450 5D	E-Series Chassis	Ford	2011	50	6/9/2020 12:06	CHANGE	ort change	SCRTD	Oil Change	ā	194440	Bus #734	7592102
1FDFE4FS5BDB05247	Bus	E-450 SD	E-Series Chassis	Ford	2011	0	6/9/2020 16;10	Tires	Taras	SCRID facility	Rotate Tires	3	194440	Bus ⊭734	7592115
1FDFE4FSS8DB05247	8us	E-450 SD	E-Scries Chassis	Ford	2011	22.4	6/9/2020 9:12	OIL CHANGE	oil change	SCRTD facility	Oll Change Battery Inspection Engine Belt Inspection Rotate Tires Brake Ped(s) Replacement Brake Rotor Replacement	13	194440	Bus #734	7570356
1FDFE4FS5BDB05247	Bus	E-450 SD	E-Series Chassis	ъ́а	2011	0	6/10/2020 9:26	Tires	Tires	SCRTD facility	Rotate Tires	5	194440	Bus #734	7236588
1FDFE4FS5BD805247	Brs	E-450 SO	E-Series Chassis	Ford	2011	0	6/10/2020 10:27	Brake Inspection	Brake	SCRTD facility	Brake inspection	Ð	194440	Bus #734	7236596
1FDFE4FSSBDB05247	Bus	GS 0579-3	E-Series Chassis	Ford	2011	116 99	7/22/2020 9:36	belt	Brake	SCRTD	Engine Belt Inspection drive shart Tic Rod End Replacement	3	197482	Bus #734	7571916
1FDFE4FS5BDB05247	Bus	E-450 SD	E-Series Chassis	Ford	2011	8	8/28/2020 10:44	OIL	oil change	SCRTD facility	Oil Change Rotate Tires Engine Belt Inspection	₽	202082	Bus #734	7667650
1FDFE4FS58DB05247	Bus	E-450 SD	E-Series Chassis	Ford	2011	106.86	9/14/2020 9:57	tune up	tune up	SCRTD facility	Spark Plugs Replacement! Spark Plug Wire Set Replacement	3	204004	Bus #734	7794117
e Vehicle VIN/SN	Vehicle Type	Vehicle	Vehicle Model	Vehicle Make	Vehicle Year	Subtotal (USD)	Started At	Reference	Labets	Vendor Name	Service Tasks	Unit	Meter	Name	Fizetio ID

	ĸ			
¥				
			₹	

Bus 743 Pictures







1612	1660	1727	1769	1778	1867	Flee	
16123553 Br	16600315 BI	17274508 BI	17696638 Bı	17757534 ВІ	18679662 BI	Fleetio ID	
Bus #743	Bus #743	Bus #743	Bus #743	Bus #743	Bus #743	Vehicle Name	
Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Watchers	
254630	256355	259962	261427	262525	268061	Meter	
≅,	∃ _{j,}	ani a	Ξ.	m	핖	Meter Unit	
Engine Oil Cooter Engine Coolant Drain & Refill [Engine Oil & Filter Replacement Brake Inspection Engine Belt Inspection Battery Inspection Tire Rotation	Fuel Pump Replacement Exhaust/Emi ssions (Miscellaneous)	Tire Replacement Tire Rotation Service Door Tire Rotation	Engine Belt Inspection Water Pump Replacement Engine Coolant Drain & Refilt	Engine Oil & Filter Replacement fuel injector service Engine Air Filter Replacement Windshield Washer Fluid Fill Engine Bett Inspection Battery Inspection Tire Rotation	Engine Oil & Filter Replacement Engine Beit Inspection Brake Inspection Fattery Inspection Tire Rotation Windshield Washer Fluid Flui Suspension System Lubricate	Service Tasks	×
SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	Vendor Name	
PM	FUEL	Door Tires	water			Labels	
Humberto	Humberto / Cruz	Humberto / Cruz / Albert	Humberto	Roman	Roman	Reference	
Albert	Albert	Albert	Albert	Ањет	Albert	Created By First Name	
Minjares	Minjares	Minjares	Minjares	Minjares	Minjares	Created By Last Name	
2/1/2023 0:00	3/1/2023 0:00	4/19/2023 0:00	5/10/2023 0:00	5/20/2023 0:00	7/18/2023 0:00	Completed At	
98.28	360,88	248,88	94,98	55.79	36.37	Parts Subtotal (USD)	
2013	2013	2013	2013	2013	2013	Vehicle Year	
Ford	Ford	Ford	Ford	Ford	Ford	Vehicle Make	
E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Cnassis	E-Series Chassis	E-Series Chassis	Vehicle Model	
E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD	Vehicle Trim	
Bus	Bus	Bus	Bus	Bus	Bus	Vehicle Type	
Out of Service	Out of Service	Out of Service	Out of Service	Out of Service	Out of Service	Vehicle Status	
1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	Vehicle VIN/SN	

14359452	14980558	14712339	14709369	14771147	15013680	15234767	15354960	15708099	15708006
Bus #743	Bus #743	Bus #743	Bus #743	Bus #743	Bus #743	Bus #743	Bus #743	Bus #743	15708006 Bus #743
Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Atbert Minjares	Albert Minjares
235747	240335	241924	242894	243086	245262	248381	248770	250725	252453
3,0	3	m.	m	∃	3	国	3	m	Ð
Engine Air Filter Replacement}Engine Air Filter Housing Clean	Ignition Coil Replacement engine oil fill	TIRE REPAIR Tire Balance	Engine Belt Inspection Brake Inspection Time Rotation Wheel Bearing Replacement Wheel Bearing Seal Replacement	Engine Oil & Filter Replacement Battery Inspection Engine Belt Inspection Brake Inspection Air Filter Replacement Brake Pad(s) Replacement fuel injector service	Exhaust/Emissions (Miscellaneous)	Engine Coolant Replacement Engine Belt Inspection Service Door	Tire Replacement Tire Balance	Windshield Washer Fluid Fill	Transmission Fluid Drain & Refill (Engine Oil & Filter Replacement) true injector service (Windshield Washer Fluid Fill Engine Belt Inspection) Tire Rotation (Brake Inspection (Battery Inspection
SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility
airfilter	ign. coil	Tires	BEARING	FRONT BRAKES P	EXHAUST	COOLANT FLUSH	Tires	Washer Fluid	PM
Спиг	Cruz	Cruz	Спи	Humberto and Cruz	Cruz	CRUZ	Cruz	humberto	Roman and Humberto
							Albert	Albert	Albert
							Minjares	Minjares	Minjares
8/17/2022 0:00	9/20/2022 0:00	10/3/2022 0:00	10/10/2022 0:00	10/12/2022 0:00	10/24/2022 0:00	11/28/2022 0:00	11/30/2022 0:00	12/22/2022 0:00	1/12/2023 0:00
14.25	14.73	6	46,39	86.58	3.12	18.18	114	3.1	96.88
2013	2013	2013	2013	2013	2013	2013	2013	2013	2013
Ford	Ford	Ford	Ford	Ford	Ford	Ford	Ford	Ford	Ford
E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis
E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD
sng	Bus	Bus	Bus	Bus	Bus	Bus	Bus	Bus	Bus
Out of Service	Out of Service	Out of Service	Out of Service	Out of Service	Out of Service	Out of Service	Out of Service	Out of Service	Out of Service
1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352

12630862	12742225	12857023	12974709	13627025	13630097	13853742	13844396
Bus #743	Bus #743	Bus #743	Bus #743	Bus #743	Bus #743	Bus #743	Bus #743
Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares
223619	224520	226358	227608	230866	231386	233917	234375
3.	В	⊒,	<u>n</u> .	3	3	<u> 1</u>	Э.
Engine Coolant Expansion Tank Replacement windshield washer nozzle Exterior Bulb Replacement	Tire Rotation Spark Plug Replacement Air Filter Replacement Ignition Coil Replacement Tire Replacement Tire Rotation	Tire Replacement Tire Balance	Engine Oil & Filter Replacement Engine Bett Inspection Battery Inspection Brake Inspection Tire Rotation; fuel injector service Suspension System Lubricate Windshield Washer Fluid Fill Exterior Bulb Replacement	Exterior Bulb Replacement Wheel Bearing Replacement Wheel Bearing Seat Replacement Brake Rotor Replacement Brake Inspection	Engine Coolant Drain & Refill Heater Hose Replacement	A/C System Evacuate & Recharge Fuel Pump Replacement	Engine Oil & Filter Replacement Engine Belt Inspection Brattery Inspection Brattery Inspection Brake Rotation Brake Inspection Air Filter Replacement Brake Pad(s) Replacement Inelinjector service Tire Replacement Tire Balance
SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility
coolant leak	SPARK PLUGS Tir es	Tires	MARKER ШGHT PM	BEARING	coolant leak	AC FUEL	ž
Humberto & Cruz	CRUZ/ HUMBERTO	Art Pena	Cruz	CRUZ	нимвекто	HUMBERTO/ CRUZ	HUMBERTO/ CRUZ
113000							
5/12/2022 14:30	5/18/2022 0:00	6/2/2022 12:00	6/11/2022 0:00	6/30/2022 0:00	7/6/2022 0:00	7/25/2022 0:00	7/28/2022 0:00
139.91	331.29	116	58.51	256.42	25,89	249.59	175.28
2013	2013	2013	2013	2013	2013	2013	2013
Ford	Ford	Ford	Ford	Ford	Ford	Ford	Ford
E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis
E-450 SD	E-450 SD	E-450 SD	E-450 SD	€-450 SD	E-450 SD	E-450 SD	E-450 SD
Bus	Bus	Bus	Bus	Bus	Bus	Виѕ	Bus
Out of Service	Outof	Out of Service	Out of Service	Out of Service	Out of Service	Out of Service	Out of Service
1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4F\$0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4F\$0 DDA09352

100	Те	H	Р	
10635676	11345522	11284799	11769629	12368173
Bus #743	Bus #743	Bus #743	Bus #743	Bus #743
Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares
198992	203863	205567	213845	220156
3.:	3	⊒,	m.	3
Engine Oil & Filter Replacement Engine Bett Inspection Tire Rotation Brake Inspection Brake Inspection Battery Inspection Air Filter Replacement Brake Pad(s) Replacement Hower Steering Hose Replacement Itelicitor Service Engine/Drive Beit(s) Replacement	Tire Replacement Exterior Bulb Replacement	Engine Bett Inspection Engine Oit & Filter Replacement Battery Inspection Brake Inspection Tire Rotation Air Filter Replacement fuel injector service Windshield Washer Fluid Fill Windshield Wiper Blade Replacement	Engine Oil & Filter Replacement [Engine Belt Inspection Battery Inspection Firske Inspection Tire Rotation Windshield Washer Fluid Fill fuel Injector service	Engine Oil & Filter Replacement [Engine Belt Inspection Battery Inspection Inspection Inspection Irake Inspection Air Filter Replacement Windshield Wiper Blade Replacement Windshield Washer Fluid Fill AC System Evacuate & Recharge
SCRTD	SCRTD facility	SCRTD facility	SCRID facility	SCRTD facility
FRONT BRAKES P M	Tires	Z.	P	P
FRONT BRAKES IP H + STEVEN	Albert & Ruben	Ruben	steven	Humberto
·				
12/2/2021 11:55	1/4/2022 11:31	1/15/2022 10:04	3/5/2022 11:17	4/16/2022 10:59
137.07	55	57.9	31.62	120.13
2013	2013	2013	2013	2013
Ford	Ford	Ford	Ford	Ford
E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis
E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD
Bus	Bus	Bus s	Bus	8US
Out of Service	Out of Service	Out of Service	Out of Service	Out of Service
1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352

876	9191563	9699	980	996	1003	1023	1026	1028	1032
8768815 B		9699852 B	9800954 B	9962227 E	10234541 Bus #743		10267797 E	10286323 E	10329856 E
Bus #743	Bus #743	Bus #743	Bus #743	Bus #743	us #743	Bus #743	Bus #743	Bus #743	
				,		Albert Minjares	Albert Minjares	Albert Minjares	Albert Minjares
148840	163370	174871	178901	180935	185515	192896	193629	194159	194351
2.	3	∄	30	7	∄	∄	⊒.	3	m.
Oil Change Engine Beit Inspection Rotate Tires Brake Inspection Battery Inspection Air Filter Replacement	Oil Change Rotate Tires Engine Belt Inspection Brake Inspection Battery Inspection Filter Replacement Tire Replacement	Oil Change Rotate Tires Engine Bett Inspection Battery Inspection Air Filter Replacement Brake Pad(s) Replacement	Brake Inspection	Tire Replacement	Oil Change Engine Belt Inspection Rotate Tires Air Filter Replacement	Battery Inspection Engine Bett inspection Brake Bett inspection Rotate Inspection Rotate Tires Air Filter Replacement Oil Change fuel injector service Suspension System Lubricate	Headlamp Bulb Replacement	wheel chair lift	Engine Bett Inspection Brake Inspection Battery Inspection A/C System Evacuate & Recharge A/C OIL MASTER SWITCH
SCRTD	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility
oil change	oil change	oil change	Brake service	Tires	oil change	oil change	bulb	wc lift	A/C SWIT
OIL CHANGE	OIL CHANGE	OIL CHANGE	Brake inspection	Tires	OIL CHANGE	Ruben	Ruben	Ruben	Ruben and Albert
1/9/2021 16:59	4/13/2021 22:00	6/25/2021 13:00	7/22/2021 8:19	8/4/2021 13:15	9/4/2021 11:43	10/13/2021 12:26	10/19/2021 12:30	10/22/2021 11:57	10/25/20218:31
72	308	58	0	567	92	75.36	14.99	ъ	41
2013	2013	2013	2013	2013	2013	2013	2013	2013	2013
Ford	Ford	Ford	Ford		Ford		Ford	Ford	Ford
E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis		E-Series Chassis	E-Series Chassis		E-Series Chassis	E-Series Chassis
E-450 SD	E-450 SD	E-450 SD	E-450 SD		E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD
Bus	Bus	Виѕ	Bus	Bus	Bus	Bus	Bus	Bus	srg
Out of Service	Out of Service	Out of Service	Out of Service	Out of Service	Out of Service	Out of Service	Out of Service	Out of Service	Out of Service
1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352

6729264	6794747	7150292	7033065	7604684	8343053	7966953	8614474		
Bus #743	Bus #743	Bus #743	Bus ⊭743	Bus #743	Bus #743	Bus #743	Bus #743		
							-		
98727	104877	110810	110811	122519	133607	133782	148840		
₽	⊒,	3,	⊉.	3,,	3,	3	₹.		
Oil Change	Oil Change	Rotate Tires	Engine Belt Inspection Engine/Drive Belt(s) Replacement Oil Change	Oil Change Rotate Tires Engine Belt Inspection Brake Inspection Battery Inspection Air Filter Replacement Tire Replacement	Oil Change Engine Belt Inspection Rotate Tires Battery Inspection Brake Inspection Air Filter Replacement	Oil Change Rotate Tires Engine Bett Inspection Battery Inspection Brake Inspection Air Filter Replacement	Oil Change Engine Bett Inspection Rotate Tires Brake Inspection Battery Inspection Air Filter Replacement Brake Pod(s) Replacement Transmission n Fluid Replacement Engine Coolant Replacement Spark Plug Replacement Disc Brake Caliper Replacement		
SCRTD	SCRTD facility	SCRTD facility	SCRTD facility	SCRTD facility	SCATD facility	SCRTD facility	SCRTD facility		
oil change	oil change	Tires	pelt	oil change	oil change	oil change	oil change		
OIL CHANGE	OIL CHANGE	Tires	belt	OIL CHANGE pm	OIL CHANGE	OIL CHANGE	oil change OIL CHANGE		
12/3/2019 17:56	2/17/2020 15:26	4/13/2020 11:53	4/14/2020 17:17	8/12/2020 17:42	10/15/2020 15:20	10/15/2020 15:26	1/9/2021 16:36		
25	45	0	86	424	55	45.99	475.96		
2013	2013	2013	2013	2013	2013	2013	2013		
Ford	Ford	Ford	Ford	Ford	Ford	Ford	Ford		
E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis	E-Series Chassis		
E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD	E-450 SD		
Bus	Bus	Bus	8us	Bus	Bus	Bus	B		
Out of Service	Out of Service	Out of Service	Out of Service	Out of Service	Out of Service	Out of Service	Out of Service		
1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4FS0 DDA09352	1FDFE4F50 DDA09352		